

FUEL THEFT INVESTIGATION REPORT

Report ID:	SISTL-FUEL-20260323_201348
Generated:	2026-03-23 20:13:48
Status:	PENDING

1. EXECUTIVE SUMMARY

This report documents a fuel alert investigation for vehicle **Z380PH**. The alert was triggered due to a **20%** fuel drop at **Dar es Salaam - Dodoma Highway**. **Investigation Result:** THEFT

Confidence Level: 85%

Recommended Action: Dispatch investigator immediately

2. VEHICLE DETAILS

Vehicle ID:	Z380PH
Location:	Dar es Salaam - Dodoma Highway
Alert Time:	2026-03-23 20:15
Fuel Drop:	20%
Driver:	John Doe

3. INVESTIGATION FINDINGS

- Fuel dropped 20% in 30 minutes while vehicle stationary
- GPS shows vehicle parked at unauthorized location
- No refueling stations within 50km
- Driver did not report any issues
- Fuel cap seal appears tampered

4. EVIDENCE SUMMARY

GPS Data: Vehicle route tracked from dispatch to current location.

Fuel Logs: Sensor readings recorded every 5 minutes.

Driver Logs: Driver behavior and stops documented.

Station Check: No authorized refueling stations in 50km radius.

5. RECOMMENDED ACTIONS

1. Immediate investigation at vehicle location
2. Interview driver and check for unauthorized passengers
3. Review CCTV footage from nearby locations
4. File incident report with authorities
5. Consider vehicle immobilization
6. Driver suspension pending investigation

*This report was generated automatically by SISTL Fuel Monitoring System.
For questions or clarifications, contact: support@sistl.support
Report ID: SISTL-FUEL-`{timestamp}`*